



State of Utah  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt  
Governor

Ted Stewart  
Executive Director

James W. Carter  
Division Director

1594 West North Temple, Suite 1210  
Box 145801  
Salt Lake City, Utah 84114-5801  
801-538-5340  
801-359-3940 (Fax)  
801-538-7223 (TDD)

July 18, 1997

Alan Wilson  
Senior Reclamation Engineer  
Hecla Mining Company  
6500 Mineral Drive  
Coeur d'Alene, Idaho 83814-8788

Re: Approval to Proceed with Tailings Underdrain Plugging Plan., Hecla Mining Company, Escalante Silver Mine, M/021/004, Iron County, Utah

Dear Mr. Wilson:

Thank you for your May 14, 1997 letter provided in response to our letter dated February 18, 1997. I copied your letter to the Bureau of Land Management (BLM) and Division of Water Quality (DWQ) for their review and comment. On June 30, 1997, we received a letter from the BLM (copy attached) formally accepting your underdrain plugging proposal. On July 18, 1997, I spoke with Dennis Fredericks of DWQ and received his verbal concurrence to proceed with the proposed plugging plan.

The Division hereby grants its formal approval to proceed with the plugging of the underdrain collection pipe, the toe drain and the decant line according to the May 14, 1997, proposed plan. Additional water quality analyses of the underdrain discharge will not be required. I apologize for the unfortunate delay in responding to your latest reply. Thank you for your continued patience and cooperation in resolving this matter. We will continue to suspend any further processing of the latest application to change the post-mining land use, until you notify us differently. Please contact me at (801) 538-5286, if you have any other questions or concerns in this regard.

Sincerely,

D. Wayne Hedberg  
Permit Supervisor  
Minerals Regulatory Program

jb

Attachments


cc: Craig L. Egerton, BLM, Cedar City DO  
Dennis Fredericks, DWQ

M021004.pip



United States Department of the Interior

BUREAU OF LAND MANAGEMENT  
CEDAR CITY DISTRICT  
BEAVER RIVER RESOURCE AREA  
176 East D.L. Sargent Dr.  
Cedar City, Utah 84720



IN REPLY REFER TO:  
UT-044  
3809  
UTU-67116

June 27, 1997

Mr. D. Wayne Hedberg  
Division of Oil, Gas, & Mining  
1594 West North Temple, Suite 1210  
Box 145801  
Salt Lake City, Utah 84114-5801

Dear Mr. Hedberg:

This letter is in regards to correspondence, dated May 14, 1997, from Hecla Mining Co. to your Division, requesting plugging of the Escalante Mill tailings pond underdrain. The tailings pond is located entirely on public lands within Secs. 3 & 10, T. 36 S., R. 17 W.

Ed Ginouves of my staff inspected the site on June 26, 1997 to confirm the surface integrity of the tailings cap and measure the flowrate of the underdrain. The tailings pond soil cap has a stable cover of vegetation and no evidence of surface water penetration of the cap was noted. The flowrate of the underdrain was measured at the discharge point at the mill and was found to be 0.5 liters/min. We are satisfied that this extremely low flowrate is an indication that the pore fluids in the tailings pile are essentially drained, and that the tailings pile cap is functioning as designed, and has isolated the tailings from the hydrologic system. It would be acceptable to BLM to plug the underflow drain pipe at this time.

If you have any questions or concerns, please contact Ed Ginouves at (801) 865-3040.

Sincerely,

  
Craig L. Egerton  
Area Manager